Inventory & Schedule of Condition

Local Property Inventory

07517 014656

pinnaclepropertyservices.co.uk@gmail.com

Property inspected by Pinnacle Property Services

Address

18 Gainsborough Square Bexleyheath DA6 8BU



Carried Out

August 3rd 2018

Contents

| Notes | 2 | 2 |
|----------------------|---|----|
| Areas | 3 | 3 |
| Meter Readings | 3 | 3 |
| Exterior Front | 4 | 1 |
| Hallway | 5 | 5 |
| Living Room | 8 | 3 |
| Kitchen | 1 | 11 |
| Bedroom 1 | 1 | 4 |
| En-Suite Shower Room | 1 | 17 |
| Bedroom 2 | 1 | 19 |
| Bedroom 3 | 2 | 21 |
| Bathroom | 2 | 23 |
| Wc | 2 | 26 |
| Garden | 2 | 27 |
| Alarms | 2 | 26 |
| Declaration | 3 | 30 |

Notes

Guidance Notes for Tenants

Check Out Report

The property will be inspected as thoroughly upon check out as it was upon check in. Obvious or significant discrepancies will be reported to the Managing Agent/Landlord. The report will record all damaged/soiled/missing items and whether in the opinion of the Clerk, the tenant is responsible and thus liable for charges. However, the law allows for Fair Wear & Tear and this will be taken into consideration when the Check Out report is compiled.

If professionally cleaned at the commencement of the tenancy, the property must be professionally cleaned (or of a similar standard) for the check out. Particular areas of note are: Sanitary ware, carpets and kitchen appliances/white goods/cupboards and work surfaces. Gardens must be left in accordance with the tenancy agreement otherwise charges may be added to the Check Out report.

At the end of the tenancy all items should be ready and in the same location as

listed in the Inventory. Failure to do so will result in handling charges being passed on to the tenant. All beds should be left unmade with the linen folded. Bedding and linen should be clean and ironed where relevant. Beds (bases & mattresses) and pillows will be examined for staining and damage not previously noted on the inventory. Charges will be made in the form of cleaning charges, compensation or a percentage of the replacement cost as appropriate.

Charges may be added to the Check Out Report if marking to walls and woodwork is found to be excessive and if crockery, china, glassware and utensils are found to be

chipped, cracked, burnt or soiled beyond what is considered Fair Wear & Tear. If the property is furnished all items will be checked for damage and charges may be incurred if damage is considered beyond Fair Wear & Tear. At the allotted time of Check Out all cleaning must be completed, personal items removed and keys handed over. Failure to comply will result in the clerk aborting the call and further charges being added to the Check Out Report.

The Inventory Clerk acts as an independent and reasonable body and will avoid any unnecessary criticism or derogatory comments when compiling or checking the inventory.

Page 2 of 31 Tenant Initials:

| 1. METER READINGS | | | |
|--------------------|---------------|---------------------------|-----------------|
| Item | Serial Number | Reading | Tenant Comments |
| 1.1 Gas Meter | Garage | 8724 | |
| 1.2 Electric Meter | Garage | Low 95828 Normal 48765 | |
| 1.3 Water Meter | Garage | 02126 | |





Ref #1






Ref #1

Page 3 of 31 Tenant Initials: _____

| 2. EXTERIOR FRONT | | | |
|-------------------|--|---|-----------------|
| Item | Description | Condition | Tenant Comments |
| 2.1 Door | Four single base cupboards with five drawers, all have matching kickboards. Four single wall units with matching plinths, one contains logic boiler. All have wooden doors with chrome effect bar handles - Light and dark brown; Black external lantern light; Black numerical 18 Black hanging basket bracket Green recycling bin and recycling boxes. White cupboard - storage for rubbish. White garage door with chrome handle | Well Maintained Skip to the front of the house. | |





Ref #2



Ref #2

Page 4 of 31 Tenant Initials: _____

| 3. HALLWAY | | | |
|----------------|---|---|-----------------|
| Item | Description | Condition | Tenant Comments |
| 3.1 Door | White upvc door with georgian glazed panel and chrome fixings. White wooden double doors with glass effect handles, 10 frosted glass panes to each door | In clean condition. The internal doors have in excess of 3 stickers to the frame. In clean condition. | |
| 3.2 Walls | Textured and painted white to the lower hallway Part wallpapered and part painted mint green to the stairs and landing | In clean condition | |
| 3.3 Ceiling | Textured and painted white with coving | In clean condition | |
| 3.4 Woodwork | Painted White | In clean condition, fixings remain | |
| 3.5 Flooring | Light oak wood flooring | In clean condition | |
| 3.6 Heating | White wall mounted radiator with end caps | In clean condition, marks to the top of the unit | |
| 3.7 Lighting | Brass/glass ceiling mounted light fitting x 3 | Good working order | |
| 3.8 Additional | White louvre doors with glass effect handles, access to cupboard housing coat hooks x 2, 1 x fused switch and 1 x single light switch. Brown access door with chrome handle, leading to the garage; 1 x Door mat; 1 x Wall mounted thermostat; 1 x Wall print; Built in cupboard with white louvre doors, glass effect handles, housing Worcester Boiler, associated pipework | In clean condition; The boiler is untested | |
| 3.9 Electrics | 1 x Chrome light switch 1 x single socket 1 x Single light switch 1 x Single socket 1 x Fused switch Capped cables in the wall at the top of the stairs. | Untested | |

Page 5 of 31 Tenant Initials: _____

3. HALLWAY (CONT.)





Ref #3










Ref #3





Ref #3


Page 6 of 31 Tenant Initials: _____


3. HALLWAY (CONT.)





Ref #3 Ref #3





Ref #3 Ref #3





Ref #3

Ref #3


Page 7 of 31 Tenant Initials: _____

| 4. LIVING ROOM | | | |
|----------------|--|--|-----------------|
| tem | Description | Condition | Tenant Comments |
| 4.1 Door | White upvc georgian french doors with white handles and yale lock. 2 x Side georgian windows with 1 opening to each. | In clean condition | |
| 4.2 Walls | Grey and white wallpaper | In clean condition | |
| 4.3 Ceiling | Textured, painted white with coving | In clean condition | |
| 4.4 Woodwork | Painted white | In clean condition | |
| 4.5 Flooring | Light oak effect flooring | In clean condition | |
| 4.6 Heating | 2 x double radiators, white with both end caps present 1 x White wooden mantle piece, marble effect hearth and back and black/brass coal effect fire. | In clean condition, 1 with radiator shelf.; The fire is untested, no damage | |
| 4.7 Lighting | 1 x Flex and bulb;4 x frosted glass and chrome wall lights;2 x Glass effect beaded light shades with flex and bulb | In working order; 1 x Bulb needs replacing to the wall light | |
| 4.8 Electrics | 1 x Honeywell thermostat 1 x Quad light switch 1 x Dimmer switch 3 x Telephone point 2 x Single socket 1 x NTL point 1 x Openreach point 1 x Fused switch 2 x Double light switch Tv Cable Tv poin | Untested | |
| 4.9 Additional | 1 x Dark wood shelf 1 x Brushed chrome door bell box 1 x Wall mounted vent Door mat 1 x White wooden louvre door, glass effect handle - access to storage cupboard with shelf | In clean condition | |
| 4.10 Furniture | Dark wood built in units with brass latch handles, comprising multiple cupboards and draws, glass display doors and shelving | In clean condition | |
| 4.11 Curtains | White voile curtains on net wire.; Green lined curtains with tassle tie backs; Dark wood curtain pole | In clean condition | |

Page 8 of 31 Tenant Initials: _____

4. LIVING ROOM (CONT.)








Ref #4



Ref #4 Ref #4











Ref #4



Ref #4

Page 9 of 31 Tenant Initials:


4. LIVING ROOM (CONT.)






Ref #4 Ref #4





Ref #4



1 (01 11 1

Page 10 of 31 Tenant Initials: _____

| 5. KITCHEN | | | |
|-------------------|---|--------------------|-----------------|
| Item | Description | Condition | Tenant Comments |
| 5.1 Walls | Tiled in brown ceramic wall tiles with decorative inserts | In clean condition | |
| 5.2 Ceiling | Textured and painted white with coving | In clean condition | |
| 5.3 Woodwork | Painted white | In clean condition | |
| 5.4 Flooring | Brown/Terracotta ceramic floor tiles | In clean condition | |
| 5.5 Lighting | 3 x Strip lights- Under cupboard. 2 x Flex and bulb | Good working order | |
| 5.6 Electrics | 3 x Double sockets 2 x Fused switches 1 x Single socket 1 x Nuair fan 1 x Triple light switch | Untested | |
| 5.7 Window(s) | White upvc georgian glazed window with 2 panes, 1 opening with white handle; White upvc georgian glazed window with 4 panes, 2 openings with white handles | In clean condition | |
| 5.8 Kitchen Units | Dark wood units with brass handles comprising:- 3 x Double wall units - part leaded glazed doors 1 x Corner wall unit 2 x Single wall units 1 x Corner base unit with dummy draw 1 x Corner base unit with carousel 2 x Single base units 3 Draws Extractor housing | In clean condition | |
| 5.9 Appliances | Cream and black integrated New world oven with 2 x chrome racks and cream handle; Brown integrated gas hob with 4 burners and dial controls; Overhead extractor with 2 x filters and light | In clean condition | |
| 5.10 Worktop | Cream Worktop | In clean condition | |
| 5.11 Sink | Cream fitted sink 1 1/2 bowl with drainer and chrome mixer tap. | In clean condition | |
| 5.12 Curtains | White net curtain on net wire | In clean condition | |

Page 11 of 31 Tenant Initials: _____

5. KITCHEN (CONT.)










Ref #5 Ref #5





Ref #5 Ref #5





Ref #5

Page 12 of 31 Tenant Initials: _

5. KITCHEN (CONT.)





Ref #5

Ref #5





Ref #5

Ref #5





Ref #5

Ref #5



Page 13 of 31 Tenant Initials: _____

| 6. BEDROOM 1 | | | |
|----------------|--|--|-----------------|
| Item | Description | Condition | Tenant Comments |
| 6.1 Door | Dark wood door with brass handle and lock White louvre doors with glass effect handles - access to the en suite shower room | In clean condition | |
| 6.2 Walls | Green wallpaper | In clean condition | |
| 6.3 Ceiling | Textured with coving - white | In clean condition | |
| 6.4 Woodwork | Painted white | In clean condition | |
| 6.5 Flooring | Light oak wood flooring | In clean condition | |
| 6.6 Heating | White wall mounted radiator with end caps present | In clean condition | |
| 6.7 Lighting | 3 x Frosted glass up-lighters | In working order | |
| 6.8 Electrics | 1 x Double light switch 1 x Telephone point 3 x Single sockets 1 x Fused switch Tv cable 1 x NTL Point 1 x Light switch | Untested | |
| 6.9 Window(s) | White upvc double glazed window with georgian glazing, 2 panes, 1 opening with white handle x 2 White upvc georgian glazed door with white handle and yale lock - Access to external balcony | Very light discolouration to the corner of the frame. In clean condition | |
| 6.10 Curtains | Net curtains on net wire 3 x Light wood curtain poles 3 x Mint green suede effect curtains | In clean condition | |
| 6.11 Furniture | Light wood built in wardrobes, 2 double, 1 glass door, 1 x In clean single with glass door and shelved unit with mirror and 6 draws. | In clean condition | |


Page 14 of 31 Tenant Initials: _____


6. BEDROOM 1 (CONT.)


















Ref #6



Page 15 of 31 Tenant Initials:

6. BEDROOM 1 (CONT.)



Ref#6

Page 16 of 31 Tenant Initials: _____

| 7. EN-SUITE SHOWER ROOM | | | |
|-------------------------|---|---|-----------------|
| Item | Description | Condition | Tenant Comments |
| 7.1 Door | White wooden louvre doors with glass effect handles | In clean condition | |
| 7.2 Walls | Tiled in peach ceramic tiles | In clean condition, small section around the shower controls is tiled differently and the grouting needs finishing off. | |
| 7.3 Ceiling | Textured, painted white | | |
| 7.4 Woodwork | Painted white | In clean condition | |
| 7.5 Flooring | Black ceramic floor tiles | In clean condition | |
| 7.6 Heating | Dimplex wall mounted light/heater | In clean condition | |
| 7.7 Lighting | Chrome and frosted glass light fitting | In working order | |
| 7.8 Additional | Shaver point Chrome and glass wall mounted shelf Wall mounted mirror White shower caddy Nuair fan | | |
| 7.9 Sink | Peach coloured ceramic sink with hot and cold chrome taps and waste | In clean condition | |
| 7.10 Shower | Pink shower tray with glass/white shower door, chrome mixer bar shower and chrome attachments | In clean condition, limescale to the fixings | |







Ref #7

Page 17 of 31 Tenant Initials:

7. EN-SUITE SHOWER ROOM (CONT.)









02 Aug 2018 08:19

Page 18 of 31 Tenant Initials: _____

| 8. BEDROOM 2 | | | |
|---------------|--|---|-----------------|
| Item | Description | Condition | Tenant Comments |
| 8.1 Door | Brown wood door with brass handle and fan light White upvc rear door with georgian glazing, 1 white handle and yale lock - access to external balcony. | In clean condition, there is a crack to the front of the door and paint marks to the fan light.; The upvc door is In clean condition | |
| 8.2 Walls | Wallpapered and painted blue | In clean condition | |
| 8.3 Ceiling | Textured with coving and painted white | In clean condition | |
| 8.4 Woodwork | Painted white | In clean condition, chips to the paintwork | |
| 8.5 Flooring | Oak wood effect flooring | In clean condition | |
| 8.6 Heating | White wall mounted radiator with end caps present | In clean condition | |
| 8.7 Lighting | Flex and bulb with glass beaded light shade | In working order | |
| 8.8 Electrics | 1 x Light switch 2 x Single sockets Tv cable | Untested | |
| 8.9 Window(s) | White upvc double glazed window with georgian glazing, 2 panes, 1 opening with white handle | In clean condition | |
| 8.10 Curtains | Blue and yellow wooden curtain poles Blue curtains Net curtains on net wire | In clean condition | |





Ref #8

Page 19 of 31 Tenant Initials: _____

8. BEDROOM 2 (CONT.)





Ref #8





Ref #8 Ref #8




Ref #8

Page 20 of 31 Tenant Initials: _____

| 9. BEDROOM 3 | | | |
|----------------|---|---|-----------------|
| Item | Description | Condition | Tenant Comments |
| 9.1 Door | Dark wood door with brass handle and fan light | In clean condition | |
| 9.2 Walls | Wall papered in cream paper and painted over | In clean condition, lightly patchy | |
| 9.3 Ceiling | Textured, painted white with coving | In clean condition | |
| 9.4 Flooring | Oak wood effect flooring | In clean condition, surface scratches evident | |
| 9.5 Heating | White wall mounted radiator with end caps | In clean condition | |
| 9.6 Lighting | Flex and bulb with glass beaded shade | Good working order | |
| 9.7 Electrics | 1 x Light switch 2 x Single sockets Tv Cable | Untested | |
| 9.8 Additional | Built in cupboard, white wooden louvre doors with glass effect handles, internally shelved with light | In clean condition | |
| 9.9 Window(s) | White upvc double glazed window with georgian glazing, 2 panes, 1 opening with white handle | In clean condition, minor marks to the frame | |
| 9.10 Curtains | Cream lined curtains White wood curtain pole White net curtain on net wire | In clean condition | |
| 9.11 Woodwork | Painted white | In clean condition | |





Ref #9

Page 21 of 31 Tenant Initials: _____


9. BEDROOM 3 (CONT.)





Ref #9






Ref #9 Ref #9



Ref #9

Page 22 of 31 Tenant Initials: _____

| 10. BATHROOM | | | |
|-----------------|---|-----------------------|-----------------|
| Item | Description | Condition | Tenant Comments |
| 10.1 Door | Dark wood door with brass handle and lock | As In clean condition | |
| 10.2 Walls | Tiled in beige ceramic tiles | In clean condition | |
| 10.3 Ceiling | Textured, painted white | In clean condition | |
| 10.4 Woodwork | Painted white | In clean condition | |
| 10.5 Flooring | Cream ceramic floor tiles | In clean condition | |
| 10.6 Heating | White wall mounted radiator with end caps present | In clean condition | |
| 10.7 Lighting | Wall mounted mirrored light fitting Chrome / frosted glass light fitting | Good working order | |
| 10.8 Additional | Chrome/white ceramic towel ring Chrome/white ceramic towel rail 2 x Floor mats Nuair vent Shaver point Wall mounted mirror Toilet brush Chrome toilet roll holder | In clean condition | |
| 10.9 Suite | White bath, white wooden panel with chrome mixer taps, shower attachment and waste; White ceramic sink with chrome mixer taps; White ceramic toilet with white plastic seat and lid and chrome flush - Cistern housed in a wooden unit. | In clean condition | |





Page 23 of 31 Tenant Initials: _____

10. BATHROOM (CONT.)







Ref #10 Ref #10





Ref #10 Ref #10









Page 24 of 31 Tenant Initials:

10. BATHROOM (CONT.)



Ref #10

Page 25 of 31 Tenant Initials: _____

| 11. WC | | | |
|-----------------|---|--|-----------------|
| Item | Description | Condition | Tenant Comments |
| 11.1 Door | Brown wood door with brass handle, vent and door stop | In clean condition | |
| 11.2 Walls | Part wall papered in cream embossed wallpaper, part tiled in terracotta ceramic wall tiles. | In clean condition | |
| 11.3 Ceiling | Textured and painted white | In clean condition | |
| 11.4 Woodwork | Painted white | In clean condition | |
| 11.5 Flooring | Terracotta floor tiles | In clean condition | |
| 11.6 Lighting | Flex and bulb Ceiling vent. | Good workingorder | |
| 11.7 Toilet | White ceramic toilet with white plastic seat and lid and chrome flush | Not clean, brown staining to the toilet bowl | |
| 11.8 Additional | Chrome toilet roll holder Blue floor mat Toilet brush | In clean condition | |





Ref #11 Ref #11





Ref #11

Page 26 of 31 Tenant Initials:

| 12. GARDEN | | | |
|-------------|--|---|-----------------|
| Item | Description | Condition | Tenant Comments |
| 12.1 Garden | Slabbed garden with fence around.; External lantern light and garden tap | As per inventory | |
| 12.2 Garage | Blue carpeted base with white walls; White wooden units for storage, housing water meter.; Beko white washing machine with dial and button controls and soap dispenser.; Gas meter Electric Meter Consumer unit | As per inventory; Washing machine not present | |





Ref #12

Ref #12





Ref #12

Ref #12


Page 27 of 31 Tenant Initials: _____

12. GARDEN (CONT.)





Ref #12 Ref #12





Ref #12 Ref #12

7 (07 11 11

Page 28 of 31 Tenant Initials: _____

| 13. ALARMS | | | | |
|-------------------------------|----------|--------------------|-----------------|--|
| Item | Location | Test Result | Tenant Comments | |
| 13.1 Smoke Alarm | Lounge | Good working order | | |
| 13.2 Smoke Alarm | Landing | Good working order | | |
| 13.3 Carbon Monoxide Alarm | Landing | Good working order | | |
| 13.4 Carbon Monoxide Alarm | Kitchen | Good working order | | |

Page 29 of 31 Tenant Initials: _____

Declaration

| I/We the undersigned, tenant / landlord affirm that if I/we do not comment on the Inventory in writing within seven days of receipt of this Inventory th | en |
|--|----|
| I/we accept the Inventory as being an accurate record of the contents and condition of the property. | |

| Signed by the | | | |
|---------------|---|---|--|
| Signature | | | |
| Print Name | | | |
| Date | 1 | / | |
| | | | |
| Signed by the | | | |
| Signature | | | |
| Print Name | | | |
| Date | / | / | |

Page 30 of 31 Tenant Initials: _____

Terms and Conditions

Terms & Conditions

This inventory provides a fair and accurate record of the contents and condition of the contents of the property and the property's internal condition.

Disclaimer

This inventory has been prepared by an inventory clerk who is not an expert in buildings, furnishings, decoration, woods, antiques or a qualified surveyor. This inventory relates only to the furniture and all the landlord's equipment and contents in the property. It is no guarantee, or report on, the adequacy of, or safety of, any such equipment or contents, merely a record that such items exist in the property at the date of preparing the inventory and the superficial condition of same.

Furniture & Furnishings (Fire) (Safety) Regulations 1988 - (1993)

The fire and safety regulation regarding furnishing, gas, electrical and similar services are ultimately the responsibility of the instructing principal. Where the Inventory notes "Fire Regulation Label Attached", this should not be interpreted to mean the item complies with the "furniture and furnishings (fire) (safety) (amendments) 1993". It is a

record that the item had a label as described or similar to that detailed in the "guide" published by the Department of Trade and Industry January 1997 (or subsequent date). It is not a statement that the item can be considered to comply with the Regulations.

Using the Inventory

The inventory will be compiled on the basis that unless stated, listed items are in good clean condition, free from obvious soiling, damage or defects. The Inventory Compilation, Check-in or Check-out will be compiled by the Clerk assuming that the Clerk is able to do so in a manner that is safe and not detrimental to their well-being. All electrical items will be tested for power only, unless the Clerk deems testing unsafe. Smoke Detectors and Security Alarms will be noted but not tested for functioning capabilities. Windows are not checked to see whether they open or not. It is the Tenants responsibility to report on non-opening windows. All static, loose or movable items in this inventory are listed as far as possible from left to right starting at the main door. Settling cracks to walls and ceilings are accepted and will not be mentioned unless necessary. All measurements are in centimetres/metres and are approximate to within 1 centimetre unless stated otherwise. Mattresses will be inspected where accessible and will not be examined should the bed be made up. Garden plants and garden livestock will not be included in the Inventory. Contents of garages and garden sheds other than gardens tools will not be listed unless they are considered to be of value in excess of ten pounds

Page 31 of 31 Tenant Initials: